# NAVIGIL

# Release Notes

Navigil Service release 1.20.0

Date: 26.6.2023

# NAVIGIL

## 1 Release summary

The release includes some small new features and smaller improvements as well as bugfixes.

## 2 Selecting the watch from the list

Bugfix – sometimes the focus was not on the active selected device

## 3 Phone Number and Country Codes

This feature is added for the notification phone numbers a country code selector if in company or group settings there is the default country selected. It will be possible to select the country from the list. This is to prevent users from not adding the country prefix in notifications. This will be later added to other phone number fields.

**Receiver phone number**

| ➕ +358 | 50 5551234 |

Currently the default country code for all the company has the be setup by Navigil so please let us know if you wish to use this feature. In group settings there is the option to update this by company admins. You can select the default country from the select list.

**Country dialing code**

Finland (FI): 358

# NAVIGIL

## 4      Home beacon Mac Address input

We have changed this input field to be just one field. It used to have separated fields for each pair of mac address numbers. This will automatically fill in the ":" in the mac address

## 5      Signal 0 --> White

Bugfix - In the maps there was an error were the signal level 0 was shown as green. It now changed to be shown as white meaning that there is no signal information available.

## 6      Home beacons dialog

It is possible to add home beacons without coordinates. This can be used if there is a wish to fully hide the home location of the watch user. This requires the usage of **Firmware 9.4** (or later when published). The Firmware can be changed from the Multidevice Settings if not defined based on company or group settings.

There is another configuration which allows the visibility of a home beacon also mean that the user is inside a safe zone. This can be setup as a configuration and requires contacting Navigil to be activated.

# 7 Watch Dashboard badge + homebeacons

The watch dashboard now reports the latest location based on the home beacon even if without coordinates. The Locate button has been changed so that it will be disabled and grayed out for 60 seconds after clicking. Locate button will start a one-off emergency tracking and there is no need to click more than one time. The location will be updated to the badges Most recent location -field and home beacon name will be shown if available. If there is a GPS coordinate then the street address is shown. Signal strength has been moved after the status data and there is a home beacon icon if the watch is connected to a beacon,.